



3

Part 3 – High Voltage Underground

DISTRIBUTION CONSTRUCTION
STANDARDS HANDBOOK

HB01-2007

Drawing Register

Number	Revision	Description
UH1-1	Deleted	Single Core 22kV XLPE, QSG Cold Shrink Joint
UH1-2	Deleted	Single Core 22kV XLPE, QSG Cold Shrink Joint
UH1-3	Deleted	Single Core 22kV XLPE, QSG Cold Shrink Joint
UH2-1	Deleted	Fuse Switch, Receptacle, Preparation Detail
UH2-2	Deleted	Fuse Switch, Receptacle, Cable Preparation
UH2-3	Deleted	Fuse Switch, Receptacle, Connector Installation
UH2-4	Deleted	Fuse Switch, Receptacle, Fitting & Clamp Detail
UH3-1	Deleted	Ringmain Isolator (AWKS Cable Adaptor)
UH3-2	Deleted	Ringmain Isolator (AWKS Cable Adaptor)
UH3-3	Deleted	Ringmain Isolator (AWKS Cable Adaptor)
UH3-4	Deleted	Ringmain Isolator (AWKS Cable Adaptor)
UH4-1	Deleted	Installation Instructions, Screened Single Core XLPE Cable 11 & 22kV w/o Armour
UH4-2	Deleted	Installation Instructions, Screened Single Core XLPE Cable 11 & 22kV w/o Armour
UH4-3	Deleted	Installation Instructions, Screened Single Core XLPE Cable 11 & 22kV w/o Armour
UH4-4	Deleted	Installation Instructions, Screened Single Core XLPE Cable 11 & 22kV w/o Armour
UH4-5	Deleted	Installation Instructions, Screened Single Core XLPE Cable 11 & 22kV w/o Armour
UH5-1	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-2	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-3	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-4	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-5	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-6	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-7	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-8	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables
UH5-9	Deleted	Installation Instructions, Transition Joint 24kV 3c Cables

General Notes

All equipment shall be installed in accordance with the manufacturer's instructions supplied with the equipment kit to which they relate.

Installer identification tags are required where provided as part of the equipment kit. The installer identification tags shall be labelled and fitted to the joint or termination equipment as per drawing R39.

All 11KV rated cable requiring transition joints shall use FJ0310 and FJ0405 joint assemblies. All 22KV rated cables requiring transition joints shall use FJ0403 joint assembly.